Summary of Takata Ballistic Testing



Test ruptures by ZIP code of repairing dealer, with approximately 95,000 tests as of September 1, 2015.